

**Service Letter**

Service letter Number	Issue Date	Revision	Revision Date
RASL-007	9/3/1997	B	1/3/2013

Subject: TBO of Rapco, Inc. electric standby clutch unit.

Applicability:

This procedure applies to all 200 and 400 series electric standby clutch units.

Inspection Compliance:

The inspection procedure listed below should be accomplished after 7 years or 2000 hours of service from the date of installation of the clutch unit.

Procedure:

1. Remove the pneumatic pump from the electric standby clutch unit.
2. Disconnect the power wires from the electric standby clutch unit.
3. Remove the electric standby clutch from the aircraft.
4. Return the electric standby clutch unit to Rapco, Inc. for overhaul or replacement.
5. Install the new FAA PMA approved or overhauled electric standby clutch unit on aircraft.
6. Complete aircraft maintenance log book entry for the work accomplished. Include a statement that shows compliance with this service letter.

Note: If you have any questions regarding this Service Letter please feel free to contact us.

