


RAPCO, inc.**REPLACEMENT AIRCRAFT PARTS CO.**

Parts for the
Beech
*Baron 55, 56,
 and 58 Series*



Brake Components:

Model	Year, S/N	Brake Assy	Part Number	Description
95-55, 95-A55 thru -C55A		30-66	RA164-02706 RA66-044 RABP-001	Disc Assembly Brake Pad Rivets
95-55, 95-A55 thru -C55A		30-93C	RA164-06106 RA66-044 RABP-001	Disc Assembly Brake Pad Rivets
B55		30-93B	RA164-06106 RA66-044 RABP-001	Disc Assembly Brake Pad Rivets
C55	TE-1 & up	30-66	RA164-02706 RA66-044 RABP-001	Disc Assembly Brake Pad Rivets
D55, D55A		30-93C	RA164-06106 RA66-044 RABP-001	Disc Assembly Brake Pad Rivets
D55A		30-66	RA164-02706 RA66-044 RABP-001	Disc Assembly Brake Pad Rivets
D55	TE-452 and up	30-66	RA164-02706 RA66-044 RABP-001	Disc Assembly Brake Pad Rivets
E55, E55A	1978	30-93B	RA164-06106 RA66-044 RABP-001	Disc Assembly Brake Pad Rivets
E55, E55A	1979 and on	30-66G	RA164-02706 RA66-044 RABP-001	Disc Assembly Brake Pad Rivets
56TC	TG-1 thru TG-83	30-69A	RA164-02706 RA66-22 RABP-001	Disc Assembly Brake Pad Rivets

RAPCO, inc.**REPLACEMENT AIRCRAFT PARTS CO.**

Parts for the
Baron, cont.

Brake Components, cont.

Model	Year, S/N	Brake Assy	Part Number	Description
A56TC	TG-84 and up	30-69	RA164-02706 RA66-22 RABP-001	Disc Assembly Brake Pad Rivets
58, 58A, 58P		30-93C	RA164-06106 RA66-044 RABP-001	Disc Assembly Brake Pad Rivets
58P	1984 and on	30-145	RA164-20806 RA66-044 RABP-001	Disc Assembly Brake Pad Rivets
58TC	1984 and on	30-145	RA164-20806 RA66-044 RABP-001	Disc Assembly Brake Pad Rivets

Filters & Vacuum Pumps:

Model	Engine	Air Pumps		Air Filters		
		Overhauled	New	Inline	Inlet (Repl. Element)	Regulator
B55 (up to TC2002)	TCM IO-470-L	442CW*	RA442CW*		RA1J7-1 (RAD9-18-1)	RAB3-5-1
B55 (TC2003 and up)	TCM IO-470-L	212CW 442CW-14*	RA216CW RA442CW-14*	RA1J4-7 RA1J4-7	RA1J2-5 (RAD9-14-5) RA1J2-5 (RAD9-14-5)	
C55	TCM IO-520-C	442CW-12*	RA442CW-12*		RA1J7-1 (RAD9-18-1)	RAB3-5-1
D55	TCM IO-520-C	242CW 442CW-12*		RA1J4-7 RA1J4-7	RA1J2-5 (RAD9-14-5) RA1J2-5 (RAD9-14-5)	
E55	TCM IO-520-C	212CW 442CW-12*	RA216CW RA442CW-12*	RA1J4-7 RA1J4-7	RA1J2-5 (RAD9-14-5) RA1J2-5 (RAD9-14-5)	
56TC (TG-1 thru TG-51)	LYC TIO-541-E	242CW 442CW*	RA442CW*		RA1J7-1 (RAD9-18-1) RA1J7-1 (RAD9-18-1)	RAB3-5-1 RAB3-5-1
56TC (TG-52 thru TG-94)	LYC TIO-541-E	242CW 442CW*	RA442CW*	RA1J4-7 RA1J4-7	RA1J2-5 (RAD9-14-5) RA1J2-5 (RAD9-14-5)	
58	TCM IO-520-C	212CW 442CW-12*	RA216CW RA442CW-12*	RA1J4-7 RA1J4-7	RA1J2-5 (RAD9-14-5) RA1J2-5 (RAD9-14-5)	
58TC	TCM TSIO-520-L	212CW 442CW-4*	RA216CW RA442CW-4*	RA1J4-7 RA1J4-7	RA1J2-6 (RAD9-14-5) RA1J2-6 (RAD9-14-5)	
58P	TCM TSIO-520-L	242CW-4 442CW-4*	RA442CW-4*	RA1J4-7 RA1J4-7	RA1J2-6 (RAD9-14-5) RA1J2-6 (RAD9-14-5)	

* Vacuum Pump For Aircraft Equipped With De-Ice.

RAPCO, inc.**REPLACEMENT AIRCRAFT PARTS CO.**
**Parts for the
Baron, cont.**
Propeller De Ice Products:
Boots & Leads

Model	Notes	Propeller	Part Number	Description/Sub Assy
55 Series		PHC-J3YF-2	RA1288-3	On Boot
		PHC-C3YF-2	4E2271-10**	RA2194-1
		Non-Air Cond.	4E2271-10**	RA2150
		BHC-J2YF-2	RA1701-7	
		BHC-C2YF-2	4E2271-10**	RA2194-2
		Non-Air Cond.	4E2271-10**	RA2150-2
C55		McCauley 2 Bl.	RA1288-3	On Boot
E55	A/C Only		4E2271-10**	RA2150-2
56 TC		HC-F3YR-2	RA1701-7	RA2067-4
		HC-F3YR-2	RA1701-7	RA1656#
		Hartzell 2 Bl.	RA1288-3	On Boot
			4E2271-10**	RA2194-2
58 Series		PHC-J3YF-2	RA1288-3	On Boot
			4E2271-10**	RA2150
		BHC-J2YF-2	RA1701-7	RA2150-2
			4E2271-10**	RA2194-2
		McCauley 2 Bl.	RA1288-3	On Boot
			4E2271-10**	RA2194-1
		D3AF32C35	RA1288-3	On Boot

Brushes/Modules

Model	Orig. Block Assy	Brush Assy	Brush Module (Qty)	Brushes (Qty)
55 Series, C55, E55 A/C	4E1387-5			RA1543-1 (2), RA1543-2 (1)
		RA2171	RA2111U (2)	RA1543-7, -5 (2)
		RA2142-1	RA2111U (3)	RA1543-7, -5 (3)
		RA2142-1	RA2111U (3)	RA1543-7, -5 (3)
		RA2162-2	RA2111U (2)	RA1543-7, -5 (2)
		RA2142-2	RA2111U (3)	RA1543-7, -5 (3)
56 TC	4E1639			RA1543-1 (2), RA1543-2 (1)
58 Series	4E1350-5			RA1543-2 (3)
		RA2146-3	RA2111U (3)	RA1543-7, -5 (3)
		RA2171	RA2111U (2)	RA1543-7, -5 (2)

Fuel Pumps:

Model	Part Number	OEM Part Number
56TC, A56TC	1D1-6	60-389010-15
58P, 58TC	1D1-6	60-389010-15

** Item Not Manufactured by Rapco, Inc.