

Contact: Mark Gaulke
Rapco, Inc.
Phone 262.367.2292
Fax 262.367-7158

445 Cardinal Lane
Hartland, WI 53029
www.rapcoinc.com

RAPCO, inc.
REPLACEMENT AIRCRAFT PARTS CO.



Press Release

Rapco, Inc. New FAA-PMA Approved Vacuum Pumps

Not Affected by Airborne Service Letter No: 72

Hartland WI, Thursday, March 20, 2008:

Rapco, Inc. NEW FAA-PMA approved vacuum pumps are **NOT Affected** by Airborne Service Letter No: 72 dated February 15, 2008. In this service letter, Airborne requires you to inspect your aircraft for Parker/Airborne Engine-Driven Air Pumps and if found, the Engine Driven Air Pump must be removed from service before next flight. Rapco, Inc. manufactures new FAA-PMA approved vacuum pumps under part numbers: RA215CC, RA216CW, RA441CC, RA441CC-3, RA441CC-7, RA441CC-9, RA441CC-17, RA441CC-23, RA442CW, RA442CW-4, RA442CW-6, RA442CW-8, RA442CW-14, and RA442CW-20. These pumps are **NOT Affected** by service letter 72.

Compliance with Airborne Service Letter 72:

- Replacing an Airborne Engine-Driven Air Pump with a Rapco, Inc. NEW FAA-PMA approved vacuum pump satisfies the requirements of Airborne Service Letter 72.
- If you need assistance in determining the correct replacement Rapco, Inc. vacuum pump part number for your application, our technical support staff will be happy to help.

For additional information or assistance, please visit www.rapcoinc.com or call 1-800-527-2726.

For Immediate Release, Thursday, March 20, 2008