



# Embraer EMB-120 Airliner




2-1479 Brake  
2-1585 Brake



2-1661 Brake

**FAA-PMA APPROVED**  
**Replacement Brake Parts**





**RAPCO FLEET SUPPORT, inc.**

**AIRCRAFT BRAKES**

465 Cardinal Lane,  
Hartland, Wisconsin 53029 U.S.A.  
(262) 367-6210 Phone  
(262) 367-6219 Fax  
[www.rapco-rfs.com](http://www.rapco-rfs.com)





## The Brake Kit fits the following:

- RFS-1479K Embraer:** EMB-120 & EMB-120RT Aircraft equipped with B.F. Goodrich P.N. **2-1479** series brakes.
- RFS-1585K Embraer:** EMB-120ER & EMB-120RT Aircraft equipped with B.F. Goodrich P.N. **2-1585** series brakes.
- RFS-1661K Embraer:** EMB-120ER & EMB-120RT Aircraft equipped with B.F. Goodrich P.N. **2-1661, 2-1585 & 2-1479** series brakes.

Rapco Fleet Support, Inc. to B.F. Goodrich Part Number cross reference:

| QTY | RFS, Inc. Part No. <sup>1</sup> | B.F. Goodrich Part No. |                           |                             | Part Description         |
|-----|---------------------------------|------------------------|---------------------------|-----------------------------|--------------------------|
|     |                                 | 2-1479                 | 2-1585                    | 2-1661                      |                          |
| 3   | RFS1015                         | 244-608                | 244-667                   | <i>Replaced by 244-742</i>  | Rotating Disc            |
| 3   | RFS1015-1                       | -                      | -                         | 244-742                     | Rotating Disc            |
| 2   | RFS2010                         | 133-717                | 133-1096                  | <i>Replaced by 133-1317</i> | Stationary Disc          |
| 2   | RFS5155                         | -                      | -                         | 133-1317                    | Stationary Disc Assembly |
| 12  | RFS3010                         | 93-438                 | 93-956                    | 93-956                      | Wear Pad                 |
| 24  | RFS78-135                       | 78-135                 | <i>Replaced by 78-364</i> | <i>Replaced by 78-364</i>   | Rivet                    |
| 24  | RFS78-364                       | -                      | 78-364                    | 78-364                      | Rivet                    |
| 1   | RFS5020 *                       | 309-21-3               | 309-44-3                  | 309-44-3                    | Pressure Plate Assembly  |

<sup>1</sup> The part numbers of individual components are identical for both the RFS-1479K, RFS-1585K.

\* These parts are sold as a Sub-Assembly with the RFS3010 Wear Pads already riveted on and is not included in the "Hot Pac" Kit.

# FAA-PMA APPROVED

## Replacement Brake Parts

**RAPCO FLEET SUPPORT, inc.**

**AIRCRAFT BRAKES**

465 Cardinal Lane, Hartland, Wisconsin 53029 U.S.A.

For a list of distributors, Please call

(262) 367-6210 Phone, 367-6219 Fax [www.rapco-rfs.com](http://www.rapco-rfs.com)

