

BULLETIN

NUMBER: RA-B-012522

DATE: January 25, 2022

Rev: -

New FAA-PMA Approved Shim Insulators



<u>Part Number</u>	<u>Replaces</u>	<u>List</u>
RA068-03300.....	Cleveland 068-03300	\$ 80.00

Rapco offers PMA approved replacement Shim Insulators. Below illustrates the comprehensive installation eligibility. Please visit our website www.rapcoinc.com for more information.

<u>Make</u>	<u>Model</u>
M7 Aerospace LLC	SA26-T, SA26-AT
Mitsubishi	MU-2B, MU-2B-10, MU-2B -15, MU-2B -20, MU-2B -25, MU-2B -26, MU-2B -30, MU-2B -35, MU-2B -36, MU-2B -26A, MU-2B -36A, MU-2B -40, MU-2B -60
Textron Aviation	3N, 3NM, 3TM, JRB-6, D18C, D18S, E18S, G18S, H18, E18S-9700, C-45G, TC-45G, C-45H, TC-45H, TC-45J or UC45J (SNB-5), RC-45J (SNB-5P), 65 (L-23F), A65, 65-80, 65-A80, 65-B80, 65-88, 65-90, 65-A90, 70, C90, C90A, C90GT, C90GTi, 65-A90-1 (JU-21A) (U-21A) (RU-21A) (RU-21D) (U-21G) (RU-21H), 65-A90-4 (RU-21E) (RU-21H), B90, E90, H90 (T44A)
Twin Commander Aircraft	500, 500A, 500B, 500U, 500S, 560-F, 680F, 680FL, 680FL(P), 680T, 680V, 680W, 681, 685, 690, 690A, 690B, 690C, 690D, 695, 695A, 695B

RAPCO, inc.

REPLACEMENT AIRCRAFT PARTS CO.



445 Cardinal Lane, Hartland, WI, 53029

Phone: (262) 367-2292 Fax: (262) 367-7158

www.rapcoinc.com