

BULLETIN

NUMBER: RA-B-031021

DATE: March 10, 2021

Rev: -



New FAA-PMA Wear Pads

Rapco offers PMA approved replacement wear pads.

Please visit our website www.rapcoinc.com for more information.

Part Number	Replaces	List
RA109-00200.....	109-00200.....	17.80
RA109-00201.....	109-00201.....	16.00
RA109-01500.....	109-01500.....	26.80

Rapco P/N	Replaces	Aircraft	Model
RA109-00200	Cleveland 109-00200	Piper Aircraft, Inc. Textron Aviation Inc.	PA-42-1000 F90 (when STC SA1510GL is installed) 99, 99A, A99A, B99, C99, 100, A100 (U-21F), B100 (when STC SA1509GL is installed) 200, 200C, 200CT, 200T, B200, B200C, B200C (C-12F), B200C (C-12R), B200C (UC-12F), B200C (UC-12M), B200CGT, B200CT, B200GT, B200T (when STC SA757GL is installed)
RA109-00201	Cleveland 109-00201	Textron Aviation Inc.	1900, 1900C, 1900C (C-12J), 1900D (when STC SA1789GL is installed)
RA109-01500	Cleveland 109-01500	Daher Aerospace	TBM 700

RAPCO, inc.

REPLACEMENT AIRCRAFT PARTS CO.



445 Cardinal Lane, Hartland, WI, 53029

Phone: (262) 367-2292 Fax: (262) 367-7158

www.rapcoinc.com