

**Service Letter**

Service letter Number	Issue Date	Revision	Revision Date
RASL-010	01/03/2023	-	-

Subject: Part marking discrepancy on RAPCO P/N RA77611 Exhaust Gaskets.

Applicability: This Service Letter is applicable to Exhaust Gasket P/N RA77611, an FAA-PMA approved part manufactured by Rapco, Inc. when installed on the following engines:
Lycoming: O-290, O-320, IO-320, O-340, O-360, HO-360-B, IO-360-A, -B, -C, HIO360-A, -B, -C,
VO-435, TVO-435, GO-480, GSO-480, ISGO-480, O-540-A, -B, -E, -G,
IO-540-A, -C, -D, -G, -J, -K, IGO-540-A, IGSO-540-A, IO-720-A

Purpose: Previously marked exhaust gaskets will display P/N RA-77611, opposed to the correct P/N RA77611

Discussion: There is no concern as the gaskets that displayed the dash after the RA have no issues with fit, form or function. All gaskets being sold from the date of this Service Letter will be marked RA77611

