

**Service Letter**

Service letter Number	Issue Date	Revision	Revision Date
RASL-012	02/08/2023	-	-

Subject: Part marking discrepancy on RAPCO P/N RA-2117-8 De-Ice Lead Harness.

Applicability: This Service Letter is applicable to Lead Harness P/N RA-2117-8, an FAA-PMA approved part manufactured by Rapco, Inc. when installed on approved aircraft applications listed on PMA Supplements #30 & #66.

Purpose: Previously marked Lead Harnesses will display P/N RA2117-8, opposed to the correct P/N RA-2117-8.

Discussion: There is no concern as the Lead Harnesses that did not display the dash after the RA have no issues with fit, form or function. From the date of this Service Letter, the part will be marked RA-2117-8.

