



Beechcraft 1900

BE1900C, BE1900D AIRLINERS



FAA-PMA APPROVED

Replacement Brake Parts



RAPCO FLEET SUPPORT, inc.

AIRCRAFT BRAKES



440 Cardinal Lane, Hartland, Wisconsin 53029 U.S.A.

For a list of distributors, Please call

(262) 367-6210 Phone, (262) 367-6219 Fax

www.rfsbrakes.com





This Brake Kit fits the following:

Beech: B-1900 Airliner, models BE1900C and BE1900D with ABS P.N. 5006749-4, 5006749-5 brake assemblies, or Beech P.N. 114-8008-3, 114-388024-1 brake assemblies.

Rapco Fleet Support, Inc. to Beech / ABS Part Number cross reference:

QTY	Rapco Fleet Support P.N.	Beech/ABS P.N.	Part Description
1	RFS5010 *	114-8008-15	Pressure Plate Sub-Assembly
1	RFS5005 *	114-8008-17	Stationary Disc Sub-Assembly
1	RFS5015 *	114-8008-21	Back Plate - Exchange Only
62	RFS3005	114-8008-53	Wear Pad
2	RFS1005	114-8008-57	Rotating Disc
2	RFS1005A	5012405	Rotating Disc - Heavy Duty
32	RFS6A14	GYR 6A-14	Rivet
32**	RFS6B5	GYR 6B-5	Rivet
28**	RFS6B11	GYR 6B-11	Rivet
1	RFS5008895-1	5008895-1	Torque Tube

* These parts are sold as a Sub-Assembly with the RFS3005 Wear Pads already riveted on. Not sold or packaged as part of RFS6749K or RFS-6749K-1. ** There are (46) - RFS6B5 & (14) - RFS6B11 in the RFS-6749K-1 kit.

FAA-PMA APPROVED
Replacement Brake Parts

RAPCO FLEET SUPPORT, inc.

AIRCRAFT BRAKES

440 Cardinal Lane, Hartland, Wisconsin 53029 U.S.A.

For a list of distributors, Please call

(262) 367-6210 Phone, (262) 367-6219 Fax

www.rfsbrakes.com

