



Aircraft Model	Pump Model	OEM Part Number	Lear Romec	Globe	Other
<b>Aerospatiale</b>					
AS-350D Astar SA360C Dauphin AS355E, AS335F, Twin Star, SA365 Dauphin 2	<b>1C45-2</b> <b>1C45-3</b> <b>1C44-1</b> <b>1C44-2</b>	350A55-1011-3			
<b>Agusta</b>					
A109,A109A,A109All	<b>2C35-3</b> <b>1C27-11</b>				
<b>Beech</b>					
A36 56TC,A56TC,58P, 58TC Baron, B60 Duke 65B80 Queen Air 65,A65,65B80,A65-8200, 70 Queen Air C90 King Air  E90 King Air  King Air A100,B100,200 99 Airliner 1900 C, D Airliner  Model 400 Beechjet (MU-300)	<b>2B7-34</b> <b>1D1-6</b>  <b>1D1-7</b> <b>1D1-8</b>  <b>1C12-1</b> <b>1D2-12</b> <b>1D2-6</b> <b>1D2-13</b> <b>1D2-7</b> <b>1D2-12</b>  <b>1C64-5</b> <b>1C7-9</b> <b>1C7-15</b>	36-920001-603 60-389010-15  50-389041-11 50-389041-9  50-389094-5 50-380177-5  50-380177-7  50-380177-5  118-389006-5 (1C27-18 Replacement cartridge) 45AS48015-3 45AS48015-2	RR12870   12850A	164A143	Beech 50-389034-3
<b>Bell</b>					
205A 205A-1   206B Jet Ranger    206L, 206L-1 Long Ranger 212,412	<b>2C12-1</b> <b>1C64-1</b>  <b>2C27-3</b> <b>2C12-1</b>  <b>1C38-1</b>   <b>1C27-10</b> <b>1C27-4</b> <b>2C27-1</b> <b>1C36-1</b> <b>2C27-1</b> <b>1C64-1</b> <b>2C27-3</b> <b>2C12-1</b>	205-060-606-3 206-062-687-101  205-060-606-3 206-062-681-101  411523478-00 206-063-602-001 411523478-00 206-062-687-101 205-060-606-3	RG12240   RG12240 RG12160	164A1666, 164A168-1, -2  164A1666, 164A168-1, -2 164A136, 164A176, 164A204, 164A212	Also replaces Airborne 1C35-1
<b>Bellanca</b>					
Viking 17-30A (TCM Engine) Viking 17-31A & 17-31ATC (Lycoming Eng.)	<b>2B6-9</b> <b>2B6-47</b>				
<b>British Aerospace</b>					
HS, 125-700A, 800A HS 125 Series Jetstream 3101	<b>2B6-72</b> (APU Fuel Pump) <b>2C40-2</b> <b>2C6-5</b>				
<b>Canadair</b>					
CL-601, CL-601-3A	<b>1B5-11</b> (Oil Pump)	601-63901-1			



Aircraft Model	Pump Model	OEM Part Number	Lear Romec	Globe	Other
<b>Cessna</b>					
208,208A Caravan I	<b>2C6-8</b>	J480053			
310,320,340,401,402	<b>1C6-10</b>	J470233		164A102	
402C B'Liner, 404 Titan	<b>2B7-29</b>	9910202-4			
411	<b>1C6-10</b>	J470233		164A102	
414A Chancellor	<b>2B7-29</b>	9910202-4			
	<b>2B7-51</b>				
421	<b>1B5-8</b>				
421A, 421B	<b>1B5-8</b>				
	<b>1C6-10</b>	J470233			
421C	<b>2B7-29</b>	9910202-4			
425 Corsair/ Conquest I	<b>2C6-3</b>	J480012			
441 Conquest, Conquest II	<b>1C12-17</b>	9910288-8	RR53710, RR53710A,D,F RR45290		Weldon 10030A, 10032A Weldon 8150A, 8150B Weldon 8150A, 8150B
500 Citation I, 550 Citation II, S550,552(T-47)	<b>1C7-12</b> <b>1C7-3</b>	9912017-3			
500 Citation I, 550 Citation II (British)	<b>1C7-13</b> <b>1C7-5</b>	9912017-4			
650 Citation III	<b>1C56-2</b> <b>1C27-14</b> (Replacement Cartridge for 1C56-2)	J453741 J062276			
<b>Construcciones Aeronauticas, SA (CASA)</b>					
212	<b>2C37-2</b> <b>2C27-2</b> (Replacement Cartridge for 2C37-2)		RR52000E & K		
<b>DeHavilland</b>					
DHC-6 Model 100, 200	<b>1D2-17</b> <b>1D2-14</b>	C6SC1005-5	RR12830A, RG12838		
DHC-6 Model 300 Twin Otter	<b>2B7-1</b>				
<b>Dornier</b>					
DO-228	<b>1C12-32</b>				
<b>Embraer</b>					
EMB-110 Bandierante	<b>2C37-1</b> <b>2C27-2</b>				
EMB-120 Brasilia	<b>1C7-17</b>				
<b>Fairchild (Swearingen)</b>					
SA226-T, -AT,-TC,-T(B) SA227-AC, -AT, -TT Metro & Merlin	<b>1C49-5</b> <b>1C49-3</b> <b>1D2-9</b>				
<b>Fairchild</b>					
F27, F27A, B, F, GJ, M FH-227, -B thru -E	<b>1C42-1</b> <b>1C27-5</b> ( Replacement Cartridge for 1C42-1)				
<b>Fokker</b>					
F27 Mark 50, 100-700	<b>1C42-1</b> <b>1C27-5</b> ( Replacement Cartridge for 1C42-1)				
<b>G.A.F.</b>					
Nomad N22, N24 Nomad N22B, N24A	<b>2B6-34</b> <b>2C6-2</b> <b>1C6-14</b>				

